

Atworth Traffic Action Group (ATAG)

Email: atag@email.com

Website: <http://atag.atpages.com>

Mobile: 07815 167095

Summary Reports of Accidents on the A365, Box Fiveways & Atworth Village 2007 to 2011

(Data Source: Wiltshire Police - Force Disclosure Unit)

(Summary document format by: ATAG Organising Committee)

A. TABLE OF ACCIDENTS

2007
V2 (car) travelling NW stopped due to stationary traffic ahead. V1 (car) travelling NW failed to stop and collided with rear of V2. A365. Vehicles 2; casualties 1; slight.
V1 (car) travelling W intending to turn right at junction. V2 (car) travelling E intending to go straight on at junction. V1 turns right into path of v2. V2 collides with v1. Junction A365 & B3109, Box Fiveways. Vehicles 2; casualties 1; slight.
V1 (car) travelling W intending to turn right went through red traffic light and turned into path of V2 (car) travelling E. V2 collided with nearside of V1. Junction A365 & B3109, Box Fiveways. Vehicles 2; casualties 1; slight.
V1 (car + trailer) travelling E, stalled, engine died so V1 stopped with no lights. V2 (car) travelling E didn't see V1 and collided with rear of V1's trailer. A365, 30m W of u/c road to Park Farm. Vehicles 2; casualties 1; slight.
2008
V2 (car) travelling W turned right at traffic light controlled junction not realising that V1 (car) travelling E had right of way. V1 collided with nearside V2. Junction A365 & B3109, Box Fiveways. Vehicles 2; casualties 1; slight.
2009
V1 (car) travelling NW lost control on LH bend, left carriageway to offside, collided with stone wall and overturned back onto carriageway. V2 (car) travelling SE then collided with overturned V1. A365 Bath Rd, 550m E of Wadswick Lane, Atworth. Vehicles 2; casualties 2; slight.
V1 (car) travelling SE lost control around left hand bend, and collided with a wall. A365, W of Clock Tower View, Atworth. Vehicles 1; casualties 1; slight.
V1 (car) travelling NW overtaking line of vehicles on their offside. V2 (car) travelling SW pulled out onto A365 turning left. V1 collided with front of V2. A365 Bath Rd entrance to Neston Park Farm Shop, Atworth. Vehicles 2; casualties 2; slight.
2010
V1 (car) travelling W turned right to leave main road across path of v2 (car) travelling E. V2 collided with nearside of V1. Junction A365 & B3109, Box Fiveways. Vehicles 2; casualties 2; slight.
V1 (car) travelling W crossed central white line into opposite c/way and collided head on with v2 (van) travelling E. Driver of V1 is suspected to have blacked out at wheel. A365, approx 25ms W of Chapel Rise, Atworth. Vehicles 2; casualties 2; slight.
V1 (car) travelling W turned right to leave A365 across path of v2 (car) travelling E on A365. V1 believed green traffic light gave him right of way not realising he must still give way to oncoming V2. Junction A365 & B3109, Box Fiveways. Vehicles 2; casualties 3; slight.
V1 (car) travelling N lost control on slippery road surface, struck nearside kerb and overturned leaving carriageway to nearside. B3109 Bradford Rd, 25m N of Box Fiveways A365. Vehicles 1; casualties 1; slight.

[2011 carried over ...]

Atworth Traffic Action Group (ATAG)

Email: atag@email.com

Website: <http://atag.atpages.com>

2011

V1 (car) travelling SW pulled out onto main road turning right and was struck on offside by V2 (car) travelling SE on A365. A365 Bath Rd, entrance to Neston Park Farm Shop, Atworth.

Vehicles 2; casualties 2; serious.

V1 (m/c) travelling N traversing A365 at junction. Whilst leaving A365 on right hand bend, V1 lost control, left carriageway to nearside and displaced rider into field. Junction Box Fiveways B3109 Bradford Rd & A365 Bath Rd.

Vehicles 1; casualties 1; serious.

V1 (van) travelling N when V2 (car) travelling SE failed to give way and pulled out from junction and collided with front n/side of V1. A365 Bath Rd junction with B3109 Bradford Rd.

Vehicles 2; casualties 1; slight.


V3 (van) parked on nearside facing W. V2 (car) travelling W overtook V3 on V3's offside. At the same time, V1 (m/c) travelling W attempted overtake of V2. V2 moved to offside forcing V1 to clip offside verge displacing rider. A365 Bath Rd, approx 260m E of Wormwood Farm.

Vehicles 3; casualties 1; slight.

B. SUMMARY FIGURES

Accidents: 16; Serious: 2; Minor: 14; Vehicles: 30; Casualties: 26.

C. MAP of LOCATIONS



The map shows the location of incidents along the A365 between Box Fiveways and Atworth village.

This document was prepared by the ATAG Organising Committee using the data and report issued by the Wiltshire Police Force Disclosure Unit following a Freedom of Information Request.

*The Atworth Traffic Action Group is a community association formed by residents of Atworth.
It's aim is to protect Atworth from the effects of traffic through the village.*